

















① x4  Q18x $\frac{1090}{42.9}$	② x12  Q18x $\frac{1070}{42.1}$	③ x20  Q18x $\frac{1070}{42.1}$
④ x10  Q18x $\frac{870}{34.3}$	⑤ x10  Q24x $\frac{1000}{39.4}$	⑥ x10  Q24x $\frac{1000}{39.4}$
⑦ x6  Q18x $\frac{520}{20.5}$	⑧ x6  Q18x $\frac{1070}{42.1}$	⑨ x1  Q18x $\frac{770}{30.3}$

Ax4	Bx6	Cx2	Dx3	Ex10	Fx10	Gx20
						


Hx1	Ix8	Jx2	mm inch
			 x10




3




4




5




6




7




8




9




10




11



12



13



14

